PRECISION AUTO EXPRESS REPAIR

Paint Repair, Auto Detailing & More

Customer Information

Name: Pittsburgh Bureau of Police

Address: Narcotics Unit
1203 Western Ave.
Pgh, PA 15233

~~Phone:~~

VIN# 1C4SDJFT8RC147649

Date: 2-17-26

Invoice #	Year	Make	Model	Color
0217263	2024	Dodge	Durango	Gray

Description	Materials	Labor	Total Price
- Front End Repair - Hood, Bumper, Headlight			
- Right Side Repair - Fender, Door			
- See attached estimate			
		Total Amount Due	$6347.85

Make Check Payable To: Precision Auto Express Repair

Thank you for your business!

Ash Huber
136 Clairton Blvd
Pleasant Hills, PA 15236

precisionautoexprepair@gmail.com
412-650-8159

Precision Auto Express Repair

Workfile ID: 26a3c50e

136 Clairton Blvd., Pleasant Hills, PA 15236
Phone: (412) 650-8159

Preliminary Supplement 1 with Summary

Customer: City Of Pgh- BRIAN SCHMITT **Job Number: 340**

Written By: Ash Huber

Insured:	City Of Pgh- BRIAN SCHMITT	Policy #:		Claim #:	
Type of Loss:		Date of Loss:		Days to Repair:	0
Point of Impact:					

Owner:
City Of Pgh- BRIAN SCHMITT

Inspection Location:
Precision Auto Express Repair
136 Clairton Blvd.
Pleasant Hills, PA 15236
Repair Facility
(412) 650-8159 Business

Insurance Company:

VEHICLE

2024 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

VIN:	1C4SDJFT8RC147649	Interior Color:		Mileage In:	Vehicle Out:
License:		Exterior Color:		Mileage Out:	
State:	PA	Production Date:		Condition:	Job #: 340

TRANSMISSION
Automatic Transmission
4 Wheel Drive
POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
DECOR
Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console
CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Dual Air Condition
Backup Camera
Parking Sensors
RADIO
AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection
Satellite Radio
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Xenon or L.E.D. Headlamps
Blind Spot Detection
SEATS
Cloth Seats
Bucket Seats
Reclining/Lounge Seats
WHEELS
Styled Steel Wheels
PAINT
Clear Coat Paint
OTHER
Rear Spoiler
California Emissions
TRUCK
Rear Step Bumper
Trailer Hitch
Trailering Package

Preliminary Supplement 1 with Summary

Customer: City Of Pgh- BRIAN SCHMITT **Job Number: 340**

2024 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

Line		Oper	Description	Part Number	Qty	Extended Price $	Labor	Paint
1	#		MAY NEED ADDITIONAL PARTS AND LABOR		1			
2	#		ONCE VEHICLE IS TORN DOWN		1			
3	**FRONT BUMPER**							
4	**	Repl	A/M CAPA RT Bumper cover upper bracket	68533282AA	1	88.00	Incl.	
5	S01		O/H front bumper				3.1	
6	S01	Repl	Bumper cover w/o prk aid	68510292AD	1	684.00	Incl.	3.0
7	S01		Add for Clear Coat					1.2
8	**	Repl	A/M CAPA Energy absorber	68533296AA	1	63.00	Incl.	
9	**GRILLE**							
10		Repl	RT Trim molding Pursuit	6UZ40DX8AA	1	45.05	Incl.	
11	**FRONT LAMPS**							
12		Repl	RT Headlamp assy w/o auto high beam black bezel	68433784AE	1	1,695.00	Incl.	
13			Aim headlamps				0.5	
14		Repl	RT Side marker lamp	68476818AA	1	43.75	0.1	
15		R&I	LT Headlamp assy w/o auto high beam black bezel				0.4	
16	**HOOD**							
17	**	Repl	A/M CAPA Hood (ALU)	55369453AF	1	701.00	1.9	3.0
18			Add for Clear Coat					1.2
19			Add for Underside(Complete)					1.5
20			Add for Clear Coat					0.3
21	**INFORMATION LABELS**							
22		Repl	Emission label 5.7 liter all	68636253AA	1	6.25	0.2	
23	**FENDER**							
24	**	Repl	A/M CAPA RT Fender	55369734AD	1	373.00	2.0	2.0
25			Overlap Major Adj. Panel					-0.4
26			Add for Clear Coat					0.3
27			Add for Edging					0.5
28			Add for Clear Coat					0.1
29		Repl	RT Fender liner rivet	6500911	2	25.60		
30	**	Repl	A/M CAPA RT Wheel flare w/o body color	57010620AF	1	185.00	0.3	
31	*	Blnd	LT Fender					1.0
32		R&I	LT Wheel flare w/o body color				0.3	
33	**FRONT DOOR**							
34	*	Blnd	RT Outer panel					1.2
35		R&I	RT Power mirror w/o memory, w/blind spot detection gloss black				0.3	
36		R&I	RT Handle, outside painted, all ceramic gray				0.3	
37	*	Rpr	RT Handle, outside painted, all ceramic gray				0.2	0.0

Preliminary Supplement 1 with Summary

Customer: City Of Pgh- BRIAN SCHMITT **Job Number: 340**

2024 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

38			R&I	RT R&I trim panel				0.4		
39		S01	Repl	RT Belt molding	55399160AE	1	128.00	0.3		
40	**MISCELLANEOUS OPERATIONS**									
41	*		Repl	Cover car/bag		1	10.00	0.2		
42	#		Subl	Hazardous waste removal		1	4.00 T			
43	#			Color tint / color match		1		0.5		
44	#		Rpr	Color sand and buff				0.5		
45	#			denib and polish		1		1.0		
46	**RADIATOR SUPPORT**									
47	**	S01	Repl	A/M CAPA RT Support bracket	68227826AA	1	127.00	0.2		
					SUBTOTALS		**4,178.65**	**12.7**		**14.9**

ESTIMATE TOTALS

Category	Basis		Rate	Cost $
Parts				4,174.65
Body Labor	12.7 hrs	@	$ 57.00 /hr	723.90
Paint Labor	14.9 hrs	@	$ 57.00 /hr	849.30
Paint Supplies	14.9 hrs	@	$ 40.00 /hr	596.00
Miscellaneous				4.00
Subtotal				6,347.85
Sales Tax				0.00
Grand Total				6347.85
Deductible				0.00
CUSTOMER PAY				**0.00**
INSURANCE PAY				