



Irvin E. Williams  
President

September 16, 2019

To Whom it May Concern:

We have reviewed the request for a flow depth measurement and submit the following attached photo with time and date stamp.

This test was performed on 9/6/19 at 7:54 am which is noted in the photo with a high-water level at 10". This was pipes incoming at 12 o'clock and discharging at 6 o'clock 42" RCP located on Dinwiddie Street and an 8" PVC Pipe location at 3 o'clock. The man hole location is (MH010N031).

Thank You

Irvin E. Williams

Enclosure: Photo